



# LOLER Report of Thorough Examination of Lifting Equipment

Issued under and complies with the Lifting Operations and Lifting Equipment Regulations 1998 following a thorough examination of lifting equipment within an interval of 6 months under LOLER regulation 9(3)(a)(i)

Issued by Rossendale Group Ltd., Portside North, Merseyton Road, Ellesmere Port, CH65 2HQ UK T: +44(0)1513555091 F: +44(0)1513572108  
E: sales@rossendalegroup.co.uk W: www.rossendalegroup.co.uk

Report No. <b>E8AP524/0002</b>
Date of this examination <b>10.04.2018</b>
<b>Pass</b>
Next examination due <b>10.10.2018</b>

<b>Employer or user for whom examination was made</b>
Balfour Beatty Civil Eng. Ltd Unit 2 Chapelton Sheffield S35 2PH

<b>Location of equipment</b>
RAF Menwith Hill

<b>Site location</b>	Balfour Beatty
----------------------	----------------

<b>Location at which examination was made, if different</b>	N/A
---	-----

<b>IDENTIFICATION MARK</b>	<b>634233 FP</b>
----------------------------	------------------

<b>Particulars sufficient to identify the equipment</b>	Lifting accessory, Generator container lifting lugs DOM 8-1966 Model MD36A
---	--

<b>SWL (Safe Working Load)</b>	<b>111500 lbs</b>
--------------------------------	-------------------

<b>Proof load applied by Rossendale Group</b>	No Proof Load Applied
---	-----------------------

<b>Colour code (where applicable)</b>	N/A
---------------------------------------	-----

<b>IS THE EQUIPMENT INSTALLED PROPERLY (WHERE APPLICABLE) AND SAFE TO OPERATE?</b>	<b>YES - Pass</b>
--	-------------------

Only where 'Yes' is reported above has this equipment on the report been thoroughly examined for any defect and been found to be of adequate strength and stability for continued use by suitably trained personnel. Defect Report below.

<b>Particulars of any defect found</b>	N/A
--	-----

<b>Recommended remedial action</b>	N/A
------------------------------------	-----

<b>Timescale for remedial action</b>	N/A
--------------------------------------	-----

<b>Defect Class</b>	N/A
---------------------	-----

<b>Date of last examination (where known)</b>	N/A
---	-----

<b>Examination and report by</b>	Jason Siner
----------------------------------	-------------

<b>Date of this report</b>	10.04.2018
----------------------------	------------

<b>Signature of examiner</b>	
------------------------------	--

<b>Client PO number</b>	CRMC0309/SC/01 4
-------------------------	---------------------

Lifting Equipment Engineer authorised by Rossendale Group (Doc RD205)